From: Sgraves@TechLawInc.com Sent: 2/29/2012 3:39:38 PM

To: "Kelley Chase" < Chase. Kelley@epamail.epa.gov>
CC: "Richard Rupert" < Rupert. Richard@epamail.epa.gov>

Subject: RE: Dimock - Residential Well HW-47

## Kelley,

Yes a sample was collected at the pressure tank and at the kitchen sink. I have no records which document the presence of a reverse osmosis unit at the residence (HW-47). The only additional info I have to add, and don't know if they are directly relevant are:

- There is an old well located near the house. This old well was not sampled.
- There was a water softener system in the basement. The "wellhead" sample was collected prior to this water softener system, while the "kitchen tap" sample was collected after this system.
- The residents noted that there is a sulfur smell present during their showers.
- The kitchen tap sample had a lot of effervescence and a slight sulfur odor.
- A propane tank (located outside of the home) was being filled during stabilization of the well.
- There is a small open drain in the basement.

The only reverse osmosis (RO) unit that I have documented is from HW-39 [Ex. 5-Personal Prince] residence), which
was sampled on 2/3/12. It was reported to have a low-flow faucet (1 gal/hour). A total metals sample
(HW39-RO) was collected from this location (HW-39).
May I ask where you received the info that led you to believe the ELS-PRICE FRANCE FRA

Suddha Graves **TechLaw**, **Inc**.

From: Kelley Chase [mailto:Chase.Kelley@epamail.epa.gov]

Sent: Wednesday, February 29, 2012 12:34 PM

**To:** Graves, Suddha **Cc:** Richard Rupert

Subject: RE: Dimock - Residential Well HW-47

## Hi Suddha -

I will be meeting with the table to morrow night along with several health professionals from ATSDR to answer questions about the high arsenic results. I wanted to double check a few things with you beforehand. I am guessing you will need to take another look at the sampler's logbook. I understand that we collected a sample at the kitchen sink and at the pressure tank. Is this correct? I have recently learned that the home has an reverse osmosis unit. This was not noted at the time of the original survey (which I conducted) or from what I can tell from your earlier e-mail - from the logbook. Is that correct? I want to be sure that I understand whether we collected a sample after the RO unit (if it exists)? It may have been installed to treat only drinking water from a separate low flow faucet (not the kitchen tap).

Thanks !!!

From: "Graves, Suddha" < Sgraves@TechLawInc.com >

To: Kelley Chase/R3/USEPA/US@EPA

Date: 02/15/2012 10:42 AM

Subject: RE: Dimock - Residential Well HW-47

Kelley,
HW47 was sampled on 2/8/12.

Ex. 6 - Personal Privacy

DIM0067277 DIM0067277

Dimock. Well is reported to be 450 feet deep, with 178 ft of casing, and it is unknown what the depth of the pump is. Water had a slight sulfur smell and was slightly effervescent. There was a pressure tank and water softener in basement. It was noted that there was sewer gas at the home.

The following screening results were collected:

## Wellhead

Alkalinity 193 mg/L Dissolved Sulfide 0.087 mg/L Ferrous Iron 2.71 mg/L Turbidity 1.4 NTU

## Kitchen Sink

Alkalinity 194 mg/L Dissolved Sulfide 0.038 mg/L Ferrous Iron 0.01 mg/L Turbidity 0.22 NTU

If you want, I have photos and scanned copies of logbooks and field data sheets.

Thanks,

Suddha Graves

TechLaw, Inc.

From: Kelley Chase [mailto:Chase.Kelley@epamail.epa.gov]

Sent: Wednesday, February 15, 2012 8:44 AM

To: Graves, Suddha

Subject: Dimock - Residential Well HW-47

Hi Suddha -

I am sending this now - so that I don't forget to ask you later.

Based on the preliminary results - we have elevated arsenic (90s ug/L) in the samples collected from HW-47.

From the well survey info collected by EPA we know the following:

- well appox 450' deep, well approx 40 yrs old, original pump
- have a softener and chlorinator (installed in the 70s)
- there are also 2 other wells on the property (one deep which is used for irrigation and one shallow hand dug well)

I would appreciate it if you could check the field logs for any additional information noted by the sample team. It would be helpful if I could get this info by noon.

Thanks - Kelley

DIM0067277 DIM0067278